

Appendix B: Photographs of Delta Levees (Chapter 4)

List of Figures

Figure 1 - Sacramento River south of Courtland, showing repair of erosion using rip-rap ..	B2
Figure 2 - Merritt Island, showing repair of erosion site using vegetation	B3
Figure 3 - Sutter Slough, showing natural vegetation on levees.....	B4
Figure 4 - Sargent-Barnhart Tract, with Brookside Subdivision mansions behind levee	B5
Figure 5 - McDonald Island, with PG&E gas storage facilities behind levee.....	B6
Figure 6 - Mildred Island, showing effect of flooding on levee	B7
Figure 7 - Upper Jones Tract, showing repair of 2004 breach with eco-bench.....	B8
Figure 8 - Byron Tract, showing stepped seismically-resistant levee	B9
Figure 9 - McDonald Island, showing PL 85-99 berm on landside.....	B10
Figure 10 - Steamboat Slough	B11

Figure 1 - Sacramento River south of Courtland, showing repair of erosion using rip-rap



Figure 2 - Merritt Island, showing repair of erosion site using vegetation



Figure 3 - Sutter Slough, showing natural vegetation on levees



Figure 4 - Sargent-Barnhart Tract, with Brookside Subdivision mansions behind levee



Figure 5 - McDonald Island, with PG&E gas storage facilities behind levee



Figure 6 - Mildred Island, showing effect of flooding on levee



Figure 7 - Upper Jones Tract, showing repair of 2004 breach with eco-bench



Figure 8 - Byron Tract, showing stepped seismically-resistant levee



Figure 9 - McDonald Island, showing PL 85-99 berm on landside



Figure 10 - Steamboat Slough

